



New Safety Recall Advanced Communication – 79C

FCA US LLC (FCA US) has announced a safety recall on certain 2026 model year (DJ) Ram 2500 Pickup, (D2) Ram 3500 Pickup, (DD) Ram 3500 Cab Chassis, and (DP) Ram 4500/5500 Cab Chassis vehicles.

REASON FOR THIS SAFETY RECALL

Some of the above vehicles may have been built with the incorrect 3.5-inch Instrument Panel Cluster (IPC) which displays the ISO symbol brake system warning light instead of "BRAKE" light. Vehicles built with IPCs that display the incorrect brake system warning light may cause a customer to not understand that a brake system problem potentially exists, which may cause a vehicle crash without prior warning.

The condition described above does not comply with Federal Motor Vehicle Safety Standard No. 101 Controls and Displays, Section 5, requires that "Each [...] vehicle [...] fitted with a control, a telltale or an indicator listed in Table 1 or Table 2 must meet the requirements of this standard for the location, identification, color, and illumination [...]." Table 1 requires that for brake system malfunction a telltale with the word "Brake" must be illuminated in red. Vehicles built with the incorrect IPC illuminates the ISO symbol brake system warning light and not the word "Brake."

SERVICE ACTION

FCA US will conduct a voluntary safety recall to replace the IPC. The remedy for this condition is not currently available. Dealers will be notified of the launch of this safety recall by way of established communication methods. This recall is estimated to launch in 3rd Quarter of 2025.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations
FCA US LLC